

<p>ADDENDUM #3 INVITATION FOR BIDS R-39 SALEM PUBLIC LIBRARY EXTERIOR IMPROVEMENTS FEBRUARY 11, 2016</p>

Specification Changes:

Section	Paragraph	Description
Masonry Repair	A,3	Delete in its entirety.
Carpentry	B,1	Add: c. Remove and install new glazing sealant at stair enclosure shown on Drawing A-3, and Note #2.
Caulking and Sealants	B	Add: "4. Alternate #1, Remove sealant at perimeter of all existing exterior windows except at rear roof skylight and rear wire glass block windows, and replace with new backer rod and sealant".
Painting	1.02	Add: 6. Alternate #2, Scrape and paint existing bracketed wood roof cornice, all sides of the building, one coat of oil base primer and two coats of acrylic latex.
	2.01, Materials	B. Add: "Exterior Metal Window Frames, Alternate #3, Primer, one coat of Sherwin Williams Kem Bond HS, Metal Primer and two finish coats of Sherwin Williams Steelmaster Alkyd Silicone #9500 Marine Industrial paint.